

## Analisis faktor potensi penyebab kecelakaan berdasarkan kondisi geometrik (studi kasus : jalan raya Bogor km 34-35)

Sari Purnamawati, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20291860&lokasi=lokal>

---

### Abstrak

Jalan Raya Bogor KM 34 ? 35 merupakan salah satu jalan di wilayah Depok yang dikenal sebagai lokasi yang sering terjadi kecelakaan. Salah satu faktor potensi penyebab kecelakaan di lokasi ini adalah dari segi kondisi geometrik jalan. Analisis faktor potensi penyebab kecelakaan dilakukan berdasarkan kondisi geometrik jalan eksisting dengan kondisi geometrik jalan yang dibutuhkan maupun kondisi geometrik jalan eksisting dengan kondisi geometrik jalan desain (perencanaan). Jika terdapat ketidaksesuaian diantaranya maka dapat menimbulkan potensi terjadinya kecelakaan.

Dari hasil penelitian ini didapatkan bahwa faktor potensi penyebab terjadinya kecelakaan di Jalan Raya Bogor KM 34-35 adalah jari - jari tikungan kondisi eksisting yang tidak memadai, superelevasi kondisi eksisting lebih kecil dari yang dibutuhkan dan daerah bebas samping di tikungan yang tidak memadai. Sehingga dibutuhkan upaya - upaya untuk mengurangi potensi terjadinya kecelakaan. Upaya yang disarankan dalam penelitian ini adalah dengan cara pemberian fasilitas perlengkapan jalan. Upaya ini diharapkan dapat mengurangi potensi terjadinya kecelakaan sebesar 40 %.

<hr>

Jalan Raya Bogor KM 34 ? 35 is one of the roads in Depok known as one of the road with high number of traffic accidents. One of the potential causes of accidents at this location is geometric conditions of the road. Factor analysis of potential causes of accidents is based on the geometric conditions of the existing road with road geometric conditions required and geometric conditions of the existing road with conditions of geometric road design (planning). If there is a mismatch among others it can lead to potential accidents.

From the results of this study found that the factor of the potential causes of accident on Jalan Raya Bogor KM 34-35 is the radius of curvature on the existing conditions is inadequate, superelevation existing condition is smaller than required and free area next to the corner is not adequate. Thus measures are needed to reduce the potential accidents. Measure suggested in this study is to extend the road facilities. This measure is expected to reduce the potential of accidents by 40%.