

# Evaluasi sarana Emergency Response Preparedness (ERP) dan Gambaran Proses Evakuasi di Gedung Pusat Administrasi (GPA) dan Maintenance Office (MO) PT Pupuk Kujang Tahun 2012 = Evaluation facility Emergency Response Preparedness (ERP) and a description of Evacuation Process in Gedung Pusat Administrasi (GPA) and the Maintenance Office building (MO) PT Pupuk Kujang in 2012

Nia Daniati, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20331515&lokasi=lokal>

---

## Abstrak

Salah satu penyebab terjadinya korban jiwa pada suatu kejadian kebakaran di gedung adalah penghuni gedung yang tidak cepat terevakuasi. Skripsi ini membahas mengenai evaluasi terhadap sarana ERP yang ada di gedung GPA dan MO PT Pupuk Kujang, serta memberikan gambaran proses evakuasi jika terjadi keadaan darurat dalam gedung tersebut. Jenis penelitian ini menggunakan desain deskriptif berdasarkan hasil observasi dan wawancara. Tujuan dari penelitian ini adalah untuk mengetahui kondisi sarana ERP di kedua gedung dan gambaran bagaimana proses evakuasi dilakukan jika terjadi keadaan darurat. Untuk sarana ERP, seperti sarana jalan keluar, pintu darurat, tangga darurat, penerangan darurat, petunjuk arah evakuasi dan tempat berkumpul belum sepenuhnya memenuhi standar yang ditentukan dari NFPA 101 dan Permen PU No. 26/PRT/M/2008. Untuk prosedur tanggap darurat, mulai dari perencanaan sampai penanggulangan sudah terdokumentasi dengan baik pada "Prosedur Emergency dan Evakuasi", namun prosedur tanggap darurat tersebut merupakan prosedur untuk tanggap darurat di pabrik, bukan di gedung. Kemudian dalam prosedur tersebut, ada beberapa elemen yang tidak sesuai dengan ketentuan dalam ISRS, yaitu jumlah personil P3K dan peralatan P3K yang masih belum mencukupi kuantitasnya. Berdasarkan hasil penelitian, penulis menyarankan agar pihak perusahaan membuat prosedur dan tim tanggap darurat gedung secara khusus, untuk meningkatkan performa kinerja K3 dan tim penanggulangan keadaan darurat dalam memenuhi semua komponen penunjang proses evakuasi di gedung. Antara lain lebih meningkatkan kegiatan inspeksi untuk sarana ERP, redesain sarana ERP bila memungkinkan, mengadakan pelatihan keadaan darurat di kedua gedung secara rutin dan menambah jumlah personil P3K.

.....One of the causes of loss of life in a fire incident in a building is a building that is not fast occupants evacuated. This study discusses the evaluation of the facility Emergency Response Preparedness (ERP) in the Gedung Pusat Administrasi (GPA) and the Maintenance Office building (MO) PT Pupuk Kujang, as well as provide an overview of the evacuation in the event of an emergency in the building. This type of research uses descriptive design based on observations and interviews. The purpose of this study was to determine the condition of the means of ERP in both the building and an idea of how the evacuation process to do if an emergency occurs. For means of ERP, as a means of escape, emergency exit, fire escape stairs, emergency lighting, evacuation directions and a assembly point not fully comply with specified standards of NFPA No. 101 and Permen PU. 26/PRT/M/2008. For emergency response procedures, ranging from planning to response has been well documented in the "Prosedur Emergency dan Evakuasi", but the procedure is an emergency response procedures for emergency response in the plant, not in the building. Later in the procedure, there are some elements that are not in accordance with the provisions of the ISRS, the number of personnel and equipment P3K are still not sufficient quantity. Based on these results, the authors

suggested that the company establish procedures and emergency response teams in particular buildings, to improve the performance of the K3 performance and emergency response team to meet all the components supporting the evacuation of the building. Among other inspection activities to further improve the means of ERP, ERP redesigning facilities when possible, emergency training in the two buildings on a regular basis and increase the number of personnel P3K.