

## Preliminary reconnaissance report of the 2011 Tohoku-Chiho Taiheiyo-Oki earthquake

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20398669&lokasi=lokal>

---

### Abstrak

The report summarizes damage associated with ground failures including landslide and liquefaction as well as non-structural damages such as to equipment and facilities, partitioning walls and ceilings, and functional failures in skyscrapers. Also brief description of the Japanese seismic design code will be provided in the Appendix. A proposed scheme of anti-tsunami design for buildings is also included.