

Jurnal Sumber Daya Air

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=120870&lokasi=lokal>

Abstrak

ABSTRAK

Many soil foundation of dams failed due to the formi g of ipe-shaped discharge channels known as piping between the soil layer and foundation . These failures may be due to subsurface or internal erosion starting near downstream toe along the base of the structure or another bulding plane