

Analisis lokasi rawan kecelakaan dan kondisi jalan sebagai upaya untuk meningkatkan keselamatan berlalulintas di Kampus Universitas Indonesia Depok = Black spot and road condition analysis as effort to improve traffic safety inside the campus of University of Indonesia, Depok

Wahyu Trihadi, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20248601&lokasi=lokal>

Abstrak

Selama tahun 2006-2009, lebih dari 200 kecelakaan lalu lintas terjadi di Kampus Universitas Indonesia. Karena itu, penelitian ini dilakukan dengan tujuan untuk memaparkan kondisi keselamatan jalan, mengidentifikasi kondisi geometrik dan jalan yang berpotensi membahayakan keselamatan pengguna jalan dan memberikan penanganan lokasi rawan kecelakaan.

Metode yang digunakan untuk mengidentifikasi lokasi rawan yaitu Angka Ekivalen Kecelakaan (AEK), sedangkan untuk analisis data kecelakaan lalu lintas menggunakan metode tabulasi silang serta untuk analisis kondisi jalan menggunakan metode Inspeksi Keselamatan Jalan (IKJ).

Hasil analisis tersebut digunakan untuk memberikan penanganan lokasi rawan berdasarkan analisis resiko. Penanganan lokasi rawan yang dilakukan berfokus pada penempatan rambu lalu lintas dan marka jalan. Lokasi rawan kecelakaan pada penelitian ini yaitu Jalan Prof. Dr. Ir. Sumantri Brodjonegoro (Tikungan PNJ), Jalan Prof. Dr. Sumitro Djojohadikusumo (Tikungan Danau Puspa), Jalan Prof. Mr. Djokosoetono (Depan Halte MUI) dan Bundaran Psikologi.

<hr><i>During 2006-2009, more than 200 traffic accidents occur on Campus University of Indonesia, Depok. Therefore, this research carried out to show road safety condition, to identify geometric and road condition that potential dangerously for road users and to give solution to handling black spot.

The method to identify black spot by using Angka Ekivalen Kecelakaan (AEK), to analyze traffic accident data by using cross tabulation, and to analyze road condition by using Inspeksi Keselamatan Jalan (IKJ). Result of these analysis are used for handle black spot based on risk analysis. Black spot handling focused on installing traffic sign and road marking. The black spot are Prof. Dr. Ir. Sumantri Brodjonegoro Road (PNJ curve), Prof. Dr. Sumitro Djojohadikusumo Road (Puspa Lake curve), Jalan Prof. Mr. Djokosoetono Road (in front of MUI bus stop) and Psychology Roundabout.</i>