

Analisa investigasi luas dan tingkat kerusakan akibat kejadian ledakan boiler furnace saat proses Refractory Dry Out (RDO) pada Unit#4 PLTU Tarahan Lampung = Investigation analysis for the extent of damage following to the boiler furnace explosion during in The Refractory Dry Out (RDO) process on Unit#4 of Tarahan Lampung

Boby Prasetyo Novidwinanto, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20517363&lokasi=lokal>

Abstrak

Analisa investigasi kegagalan / kerusakan menuntut keterlibatan Insinyur pada disiplin bidangnya masing-masing untuk dapat mencapai sasaran yang ingin dicapai dari hasil pembahasannya. Laporan ini mencakup analisa luas dan tingkat kerusakan akibat kejadian ledakan Boiler Furnance pada saat proses Refractory Dry Out (RDO) dari hasil investigasi yang telah dilakukan dalam kegiatan Praktek Keinsinyuran di P2M DTM FTUI untuk menangani proyek investigasi kejadian pada Unit#4 di lokasi PLTU Tarahan Lampung.Investigations of any failure / damage analysis require competent engineer on each respective field to achieve the setting objectives. This report concerns with the analysis for the extent of damage on the above mentioned subject as a consultant engineering practice field at P2M DTM FTUI institution for completion of investigation project following to the incident at Unit#4 Tarahan Lampung Coal Fired Power Plant.