

Kajian disain fisik ruangan dan fasilitas ruang rawat inap Rumah Sakit Medika Galaxi - Bekasi

Toding, Florida Irene, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=77703&lokasi=lokal>

Abstrak

Penelitian ini dilatarbelakangi oleh pembangunan Rumah Sakit Medika Galaxi yang tidak terencana sehingga mengakibatkan timbulnya banyak kendala dalam pengoperasiannya- Kendala utama yang dihadapi adalah kekurangan ruang rawat untuk pasien dengan jenis penyakit tertentu dan pasien dari kelompok atau golongan tertentu. Untuk mengatasi masalah tersebut, pihak manajemen merencanakan untuk tetap memanfaatkan bangunan yang ada.

Masalah yang dihadapi adalah apakah kondisi bangunan fisik dan sarana yang ada di Rumah Sakit Medika Galaxi saat ini sudah memadai dalam memenuhi kebutuhan pelayanan terhadap pasien rawat inap.

Tujuan penelitian ini adalah untuk mendapatkan gambaran tentang kondisi bangunan dan sarana fisik Rumah Sakit Medika Galaxi yang ada saat ini dalam hubungannya dengan kebutuhan ruangan bagi pasien rawat inap.

Rancangan penelitian yang digunakan adalah analisis deskriptif terhadap lima faktor utama yang mempunyai pengaruh terhadap disain ruang rawat inap serta perbandingannya dengan standar yang berlaku. Faktor-faktor tersebut adalah jumlah tempat tidur, pembagian kelas perawatan, luas ruang rawat, jenis pelayanan medik, dan fasilitas ruangan.

Jumlah tempat tidur perkelas, luas ruang rawat, jenis pelayanan medik, dan fasilitas ruangan secara umum dipandang sudah memadai sedangkan pembagian kelas perawatan belum memadai. Janis pelayanan medik dan fasilitas ruangan sudah memenuhi standar sedangkan jumlah tempat tidur total, pembagian kelas perawatan, dan luas ruangan belum memenuhi standar yang berlaku.

Faktor utama yang belum mendukung kebutuhan pelayanan rawat inap adalah pembagian kelas perawatan yang berkaitan erat dengan belum terpenuhinya kapasitas tempat tidur total di Rumah Sakit Medika Galaxi. Ukuran luas masing-masing ruang rawat belum ada yang memenuhi standar dan beberapa ruangan kelas perawatan berisi jumlah tempat tidur yang tidak sesuai dengan standar maksimal yang berlaku.

Untuk memenuhi kebutuhan pelayanan pasien rawat inap dan kemungkinan pengembangannya saat ini dan dimasa yang akan datang maka pihak manajemen Rumah Sakit Medika Galaxi perlu memperbaiki kondisi yang ada melalui suatu studi kelayakan yang komprehensif.

*Study on Physical Design and Facilities of Medika Galaxi Hospital Inpatient Room*The study background arise from the construction of Medika Galaxi Hospital which is not planned and causes many problems in operation. The primary problem was inadequacy of inpatient rooms expecially for patient with

specific condition and for patient from specific gender or different socioeconomic status. To solve the problem, the management wants to renovate the existing building.

The facing problem are where the physical condition and facility of Medika Galaxi Hospital at this time are adequate enough to comply with the need for inpatient care.

The purpose of this study are to draw a picture about Medika Galaxi Hospital physical condition & facility in conjunction with the need of rooms for inpatient care.

Study design are descriptive analytic of five primary factors which having influence to the design of inpatient room and it's comparison with standard requirements. The factors are number of patient bed, inpatient class division, size of inpatient room, classification of medical care, and room facilities.

Number of patient bed for each inpatient class, size of inpatient room, classification of medical care, and room facilities are generally accepted adequate enough but inpatient class division were not adequate. Classification of medical care and room facilities have comply with standard requirements but total number of patient bed, inpatient class division, and size of inpatient room do not comply with standard requirements.

The primary factor that not support the need for inpatient care are inpatient class division which is related largely with the total patient bed capacity of Medika Galaxi Hospital. The size of each inpatient room do not fulfill the standard requirements and some of the rooms were loaded with patient bed in quantity larger then the maximal standard requirements.

To comply with the need for inpatient care and the development possibility in this time and in the future, the Medika Galaxi Hospital management need to improve the present condition via a comprehensive feasibility study.</i>