


Lampiran 1

Characteristics Particulate Matter




Lampiran 2

Tobacco Chemistry

by Erowid

NAME :	Nicotine
CHEMICAL NAME :	(S)-3-(1-Methyl-2-pyrrolidinyl)pyridine
ALTERNATE CHEMICAL NAMES :	1-methyl-2-(3-pyridyl)pyrrolidine; β -pyridyl-alpha-N-methylpyrrolidine
ALTERNATE CHEMICAL NAMES :	Habitrol; Nicabate; Nicoderm; Nicolan; Nicopatch; Nicotell TTS; Nicotinell; Tabazur.
CHEMICAL FORMULA	C ₁₀ H ₁₄ N ₂
MOLECULAR WEIGHT	162.23
BOILING POINT₇₄₅	247° C
BOILING POINT₁₇	123-125° C
LD₅₀	(mice) .3 mg/kg iv; 9.5 mg/kg i.p.; 230 mg/kg oral

From the Merck Index 12th Edition



[Nicotine Material Safety Data Sheets \(various\)](#)

Lampiran 3

TGS 2600 - for the detection of Air Contaminants

Features:

- * Low power consumption
- * High sensitivity to gaseous air contaminants
- * Long life and low cost
- * Uses simple electrical circuit
- * Small size

The sensing element is comprised of a metal oxide semiconductor layer formed on an alumina substrate of a sensing chip together with an integrated heater. In the presence of a detectable gas, the sensor's conductivity increases depending on the gas concentration in the air. A simple electrical circuit can convert the change in conductivity to an output signal which corresponds to the gas concentration.

The **TGS 2600** has high sensitivity to low concentrations of gaseous air contaminants such as hydrogen and carbon monoxide which exist in cigarette smoke. The sensor can detect hydrogen at a level of several ppm. Figaro also offers a microprocessor (FIC02667) which contains special software for handling the sensor's signal for appliance control applications.

Due to miniaturization of the sensing chip, TGS 2600 requires a heater current of only 42mA and the device is housed in a standard TO-5 package.


The figure below represents typical sensitivity characteristics, all data having been gathered at standard test conditions (see reverse side of this sheet). The Y-axis is indicated as sensor resistance ratio (Rs/Ro) which is defined as follows:

Rs = Sensor resistance in displayed gases at various concentrations

Ro = Sensor resistance in fresh air

Applications:

- * Air cleaners
- * Ventilation control
- * Air quality monitors




The figure below represents typical temperature and humidity dependency characteristics. Again, the Y-axis is indicated as sensor resistance ratio (Rs/Ro), defined as follows:


Rs = Sensor resistance in fresh air at various temperatures/humidities

Ro = Sensor resistance in fresh air at 20°C and 65% R.H.

Sensitivity Characteristics:




Temperature/Humidity Dependency:



Basic Measuring Circuit:

The sensor requires two voltage inputs: heater voltage (V_H) and circuit voltage (V_c). The heater voltage (V_H) is applied to the integrated heater in order to maintain the sensing element at a specific temperature which is optimal for sensing. Circuit voltage (V_c) is applied to allow measurement of voltage (V_{out}) across a load resistor (R_L) which is connected in series with the sensor. DC voltage is required for the circuit

voltage since the sensor has a polarity. A common power supply circuit can be used for both V_c and V_H to fulfill the sensor's electrical requirements. The value of the load resistor (R_L) should be chosen to optimize the alarm threshold value, keeping power consumption (P_s) of the semiconductor below a limit of 15mW. Power consumption (P_s) will be highest when the value of R_s is equal to R_L on exposure to gas.



Specifications:

	Model number			TGS 2600-B00					
	Sensing element type			D1					
	Standard package			TO-5 metal can					
	Target gases			Air contaminants					
	Typical detection range			1 ~ 30 ppm of H ₂					
Standard circuit conditions	Heater voltage	V_H	5.0 ± 0.2 V DC/AC						
	Circuit voltage	V_c	5.0 ± 0.2 V DC	$P_s \leq 15$ mW					
	Load resistance	R_L	Variable	$0.45\text{k}\Omega$ min.					
Electrical characteristics under standard test conditions	Heater resistance	R_H	approx. 83Ω at room temp. (typical)						
	Heater current	I_H	42 ± 4 mA						
	Heater power consumption	P_H	210 mW	$V_H = 5.0$ V DC					
	Sensor resistance	R_s	$10\text{k} \sim 90\text{k}\Omega$ in air						
	Sensitivity (change ratio of R_s)	0.3~0.6	$\frac{R_s(10\text{ppm of H}_2)}{R_s(\text{air})}$						
Standard test conditions	Test gas conditions		normal air at $20 \pm 2^\circ\text{C}$, $65 \pm 5\%$ RH						
	Circuit conditions		$V_c = 5.0 \pm 0.01$ V DC $V_H = 5.0 \pm 0.05$ V DC						
	Conditioning period before test		7 days						

The value of power consumption (P_s) can be calculated by utilizing the following formula:


$$P_s = \frac{(V_c - V_{out})^2}{R_s}$$

Sensor resistance (R_s) is calculated with a measured value of V_{out} by using the following formula:

$$R_s = \frac{V_c \times R_L}{V_{out}} - R_L$$


For information on warranty, please refer to Standard Terms and Conditions of Sale of Figaro USA Inc. All sensor characteristics shown in this brochure represent typical characteristics. Actual characteristics vary from sensor to sensor. The only characteristics warranted are those in the Specification table above.

Structure and Dimensions:



Pin connection:
1: Heater
2: Sensor electrode (-)
3: Sensor electrode (+)
4: Heater

FIGARO USA, INC.
121 S. Wilke Rd. Suite 300
Arlington Heights, IL 60005
Phone: (847)-832-1701
Fax: (847)-832-1705
e-mail: figarousa@figarosensor.com

Lampiran 4

Lampiran 5

$\Delta T=0$

Second	Rgas/Rair	ppm
30	0.4	91.16
60	0.41	85.45
90	0.42	80.09
120	0.42	80.09
150	0.43	75.07
180	0.44	70.37
210	0.46	61.82
240	0.47	57.95
270	0.48	54.32
300	0.51	44.73
330	0.5	47.72
360	0.51	44.73
390	0.52	41.93
420	0.55	34.53
450	0.55	34.53
480	0.56	32.36
510	0.57	30.33
540	0.61	23.42
570	0.6	24.98
600	0.6	24.98
630	0.61	23.42
660	0.65	18.07
690	0.63	20.57
720	0.6	24.98
750	0.71	12.26
780	0.72	11.49
810	0.73	10.77
840	0.75	9.46
870	0.77	8.31
900	0.77	8.31

$\Delta T=10$ plat panas dibawah

Second	Rgas/Rair	ppm
30	0.44	70.37
60	0.44	70.37
90	0.52	41.93
120	0.53	39.30
150	0.53	39.30
180	0.51	44.73
210	0.54	36.84
240	0.55	34.53
270	0.57	30.33
300	0.6	24.98
330	0.57	30.33
360	0.63	20.57
390	0.52	41.93
420	0.65	18.07
450	0.58	28.43
480	0.63	20.57
510	0.69	13.95
540	0.64	19.28
570	0.72	11.49
600	0.62	21.95
630	0.73	10.77
660	0.72	11.49
690	0.77	8.31
720	0.76	8.87
750	0.74	10.09
780	0.8	6.85
810	0.76	8.87
840	0.82	6.01
870	0.81	6.42
900	0.82	6.01

$\Delta T=20$ plat panas dibawah

Second	Rgas/Rair	ppm
30	0.5	47.72
60	0.49	50.91
90	0.49	50.91
120	0.54	36.84
150	0.56	32.36
180	0.53	39.30
210	0.51	44.73
240	0.61	23.42
270	0.58	28.43
300	0.64	19.28
330	0.62	21.95
360	0.61	23.42
390	0.72	11.49
420	0.67	15.88
450	0.77	8.31
480	0.77	8.31
510	0.81	6.42
540	0.77	8.31
570	0.81	6.42
600	0.85	4.95
630	0.88	4.08
660	0.93	2.95
690	0.93	2.95
720	0.9	3.58
750	0.89	3.82
780	0.91	3.36
810	0.92	3.15
840	0.92	3.15
870	0.9	3.58
900	0.93	2.95

 $\Delta T=30$ plat panas dibawah

Second	Rgas/Rair	ppm
30	0.49	50.91
60	0.5	47.72
90	0.48	54.32
120	0.5	47.72
150	0.65	18.07
180	0.6	24.98
210	0.66	16.94
240	0.72	11.49
270	0.62	21.95
300	0.68	14.88
330	0.73	10.77
360	0.71	12.26
390	0.81	6.42
420	0.8	6.85
450	0.83	5.64
480	0.84	5.28
510	0.81	6.42
540	0.77	8.31
570	0.84	5.28
600	0.79	7.30
630	0.69	13.95
660	0.83	5.64
690	0.89	3.82
720	0.91	3.36
750	0.97	2.28
780	0.99	2.00
810	1	1.88
840	0.98	2.14
870	0.92	3.15
900	0.97	2.28

$\Delta T=40$ plat panas dibawah

Second	Rgas/Rair	ppm
30	0.53	39.30
60	0.56	32.36
90	0.59	26.65
120	0.63	20.57
150	0.63	20.57
180	0.64	19.28
210	0.68	14.88
240	0.68	14.88
270	0.71	12.26
300	0.72	11.49
330	0.74	10.09
360	0.75	9.46
390	0.73	10.77
420	0.74	10.09
450	0.76	8.87
480	0.78	7.79
510	0.78	7.79
540	0.82	6.01
570	0.82	6.01
600	0.84	5.28
630	0.85	4.95
660	0.87	4.35
690	0.88	4.08
720	0.89	3.82
750	0.88	4.08
780	0.89	3.82
810	0.9	3.58
840	0.92	3.15
870	0.93	2.95
900	0.92	3.15

 $\Delta T=50$ plat panas dibawah

Second	Rgas/Rair	ppm
30	0.57	30.33
60	0.56	32.36
90	0.63	20.57
120	0.61	23.42
150	0.65	18.07
180	0.71	12.26
210	0.69	13.95
240	0.75	9.46
270	0.75	9.46
300	0.73	10.77
330	0.81	6.42
360	0.82	6.01
390	0.74	10.09
420	0.81	6.42
450	0.85	4.95
480	0.89	3.82
510	0.84	5.28
540	0.85	4.95
570	0.91	3.36
600	0.92	3.15
630	0.89	3.82
660	0.95	2.59
690	0.95	2.59
720	0.95	2.59
750	0.95	2.59
780	0.95	2.59
810	0.97	2.28
840	0.97	2.28
870	0.97	2.28
900	0.97	2.28

$\Delta T=60$ plat panas dibawah

Second	Rgas/Rair	ppm
30	0.63	20.57
60	0.62	21.95
90	0.66	16.94
120	0.65	18.07
150	0.66	16.94
180	0.69	13.95
210	0.68	14.88
240	0.7	13.08
270	0.67	15.88
300	0.74	10.09
330	0.74	10.09
360	0.76	8.87
390	0.77	8.31
420	0.77	8.31
450	0.77	8.31
480	0.79	7.30
510	0.82	6.01
540	0.83	5.64
570	0.83	5.64
600	0.86	4.64
630	0.88	4.08
660	0.87	4.35
690	0.89	3.82
720	0.87	4.35
750	0.9	3.58
780	0.92	3.15
810	0.93	2.95
840	0.92	3.15
870	0.93	2.95
900	0.94	2.77

 $\Delta T=10$ plat panas diatas

Second	Rgas/Rair	ppm
30	0.44	70.37
60	0.45	65.96
90	0.46	61.82
120	0.51	44.73
150	0.48	54.32
180	0.52	41.93
210	0.5	47.72
240	0.49	50.91
270	0.49	50.91
300	0.52	41.93
330	0.52	41.93
360	0.57	30.33
390	0.58	28.43
420	0.64	19.28
450	0.59	26.65
480	0.65	18.07
510	0.65	18.07
540	0.61	23.42
570	0.63	20.57
600	0.66	16.94
630	0.66	16.94
660	0.62	21.95
690	0.67	15.88
720	0.77	8.31
750	0.75	9.46
780	0.72	11.49
810	0.71	12.26
840	0.75	9.46
870	0.78	7.79
900	0.79	7.30

$\Delta T=20$ plat panas diatas

Second	Rgas/Rair	ppm
30	0.45	65.96
60	0.5	47.72
90	0.55	34.53
120	0.57	30.33
150	0.56	32.36
180	0.58	28.43
210	0.56	32.36
240	0.59	26.65
270	0.62	21.95
300	0.6	24.98
330	0.57	30.33
360	0.62	21.95
390	0.65	18.07
420	0.69	13.95
450	0.71	12.26
480	0.72	11.49
510	0.74	10.09
540	0.75	9.46
570	0.74	10.09
600	0.76	8.87
630	0.71	12.26
660	0.76	8.87
690	0.81	6.42
720	0.82	6.01
750	0.84	5.28
780	0.85	4.95
810	0.81	6.42
840	0.88	4.08
870	0.87	4.35
900	0.88	4.08

 $\Delta T=30$ plat panas diatas

Second	Rgas/Rair	ppm
30	0.53	39.30
60	0.53	39.30
90	0.52	41.93
120	0.53	39.30
150	0.54	36.84
180	0.54	36.84
210	0.58	28.43
240	0.59	26.65
270	0.64	19.28
300	0.6	24.98
330	0.63	20.57
360	0.67	15.88
390	0.68	14.88
420	0.67	15.88
450	0.7	13.08
480	0.71	12.26
510	0.74	10.09
540	0.79	7.30
570	0.81	6.42
600	0.73	10.77
630	0.79	7.30
660	0.82	6.01
690	0.79	7.30
720	0.83	5.64
750	0.85	4.95
780	0.91	3.36
810	0.88	4.08
840	0.89	3.82
870	0.88	4.08
900	0.86	4.64

$\Delta T=40$ plat panas diatas

Second	Rgas/Rair	ppm
30	0.57	30.33
60	0.56	32.36
90	0.52	41.93
120	0.58	28.43
150	0.58	28.43
180	0.62	21.95
210	0.61	23.42
240	0.67	15.88
270	0.71	12.26
300	0.71	12.26
330	0.72	11.49
360	0.75	9.46
390	0.77	8.31
420	0.77	8.31
450	0.81	6.42
480	0.81	6.42
510	0.86	4.64
540	0.83	5.64
570	0.84	5.28
600	0.87	4.35
630	0.86	4.64
660	0.88	4.08
690	0.9	3.58
720	0.9	3.58
750	0.9	3.58
780	0.9	3.58
810	0.9	3.58
840	0.9	3.58
870	0.9	3.58
900	0.9	3.58

 $\Delta T=50$ plat panas diatas

Second	Rgas/Rair	ppm
30	0.58	28.43
60	0.58	28.43
90	0.6	24.98
120	0.61	23.42
150	0.58	28.43
180	0.63	20.57
210	0.69	13.95
240	0.68	14.88
270	0.72	11.49
300	0.71	12.26
330	0.74	10.09
360	0.66	16.94
390	0.69	13.95
420	0.79	7.30
450	0.81	6.42
480	0.86	4.64
510	0.87	4.35
540	0.83	5.64
570	0.88	4.08
600	0.93	2.95
630	0.96	2.43
660	0.98	2.14
690	0.97	2.28
720	0.91	3.36
750	0.94	2.77
780	0.97	2.28
810	0.99	2.00
840	1.02	1.65
870	1.02	1.65
900	1.02	1.65

$\Delta T=60$ plat panas diatas

Second	Rgas/Rair	ppm
30	0.67	15.88
60	0.65	18.07
90	0.75	9.46
120	0.73	10.77
150	0.63	20.57
180	0.69	13.95
210	0.78	7.79
240	0.71	12.26
270	0.78	7.79
300	0.74	10.09
330	0.8	6.85
360	0.86	4.64
390	0.83	5.64
420	0.85	4.95
450	0.87	4.35
480	0.87	4.35
510	0.89	3.82
540	0.91	3.36
570	0.92	3.15
600	0.9	3.58
630	0.94	2.77
660	0.95	2.59
690	0.94	2.77
720	0.94	2.77
750	0.94	2.77
780	0.94	2.77
810	0.94	2.77
840	0.94	2.77
870	0.94	2.77
900	0.94	2.77