

# Tinjauan Tingkat Keselamatan Berkendara Anggota Yamaha Vixion Club Indonesia Chapter Cikarang = Review The Level Of Safety Riding A Member Of Yamaha Vixion Club Indonesia Cikarang Chapter

Aditia Nugrahadi, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20346214&lokasi=lokal>

---

## Abstrak

Skripsi ini membahas mengenai tingkat pemakaian alat pelindung diri pada anggota yamaha vixion club Indonesia chapter Cikarang, disamping itu skripsi ini juga membahas mengenai tingkat pemenuhan persyaratan teknis dan laik jalan kendaraan anggota yamaha vixion club indonesia chapter cikarang. Penelitian ini merupakan penelitian kualitatif dengan design deskriptif. Hasil dari penelitian ini mengambarkan bahwa seluruh anggota anggota yamaha vixion club Indonesia chapter Cikarang menggunakan seluruh alat pelindung diri dengan baik dan benar namun ketidaksesuaian banyak ditemukan pada sepeda motor yang digunakan oleh anggota anggota yamaha vixion club Indonesia chapter Cikarang seperti tidak memiliki spakbor, ukuran lampu rem yang tidak sesuai, dan suara klakson yang tidak normal. Sosialisasi undang-undang nomor 22 tahun 2009 tentang lalu lintas merupakan upaya yang harus dijalankan agar kendaraan yang dimiliki oleh para anggota memenuhi persyaratan teknis dan laik jalan.

.....This research deals with the use of personal protective equipment on member of yamaha vixion club indonesia cikarang chapter, beside that this research also deals with the level of technical eligibility and be eligible to road vehicles member of yamaha vixion club indonesia cikarang chapter. This research is qualitative descriptive interpretive. The results of this research describe that all member of yamaha vixion club indonesia cikarang chapter uses all means of personal protection equipment well and properly but the discrepancy is found on a motorbike used by the members, like do not have mudguards, size brake lights that do not comply, and the abnormal sound of the Horn. Socialization of Act No. 22 of 2009 about traffic is an effort that must be running in order for the vehicles that are owned by the members of the technical requirements and be eligible to the