

## Rancangan pengembangan unit laundry rumah sakit "X" tahun 2013 = Design of development laundry unit at "X" Hospital in 2013

Rahayu Susilowati, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20348698&lokasi=lokal>

---

### Abstrak

Peningkatan status Rumah Sakit "X" belum diikuti pengembangan unit laundry Rumah Sakit. Tujuan penelitian menyusun rancangan pengembangan unit laundry dengan metode kualitatif melalui studi kepustakaan dan benchmarking, observasi, penimbangan, telaah dokumen, wawancara dan konsultasi ahli. Hasil penelitian : Volume pekerjaan linen 365kg/hari.

Sumber Daya Manusia: restrukturisasi, penambahan kualitas dan kuantitas.

Lokasi: di zona servis, semi terbatas ; akses mudah dilalui trolley. Bangunan gedung permanen, konsep horisontal. Luas 315 m<sup>2</sup>.

Sarana: 15 ruangan, tata letak sesuai alur proses linen.

Prasarana : instalasi listrik, air bersih, air limbah, uap (boiler).

Peralatan : 2 mesin cuci kapasitas 30 kg, 2 mesin pengering kapasitas 23 kg, 1 mesin roller kecepatan 70 kg perjam dan mesin press. Menerapkan konsep sentralisasi dalam pelayanan, monitoring dan evaluasi.

Saran: untuk menerapkan sentralisasi linen.

<hr><i>The Increment status of the "X" Hospital has not yet followed by the development of the Hospital laundry unit. Draft research purposes laundry unit development with qualitative methods through the study of literature and comparative benchmarking Hospital with observation techniques, weighing, study documents, interviews and expert consultation.

RESULTS: The volume of work 365 kg of linen.

Human resources: laundry units to be upgraded both quality and quantity.

Location: in the service zones, semi-limited; easy access through trolley. Permanent buildings, the concept of horizontal. Spacious 315 m<sup>2</sup>.

Means: 15 rooms, room layout process flow linen suit.

Infrastructure: the installation of electricity, water, waste water (WWTP), steam (boiler).

Equipment: 2 30 kg capacity washing machine, drying machine 2 capacity 23 kg, 1 kg machine roller speed of 70 mph and a press machine. Applying the concept of centralization of linen in service, monitoring and evaluation.

Suggestions to management to implement centralized linen in the hospital.</i>