

Standard Operational Procedures (SOP) dalam Melaksanakan Strategi Meningkatkan Maturity Level Budaya Mutu Pada Perusahaan Jasa Pelaksana Konstruksi Swasta Nasional di PT X = Standard Operational Procedures (SOP) In Implementing Strategies To Increase The Maturity Level Of Quality Culture In The National Private Construction Companies At PT X

Anna Elvarita, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20524987&lokasi=lokal>

Abstrak

Abstrak: Tujuan dari penulisan ini adalah untuk membuat rekomendasi SOP dalam melaksanakan strategi yang diperlukan untuk meningkatkan maturity level yang mempengaruhi budaya mutu di PT X. Berdasarkan tinjauan literatur tingkat kematangan budaya mutu dan penilaian validitas isi dan konstruk dari pakar/ ahli, 5 variabel untuk mengukur maturity level budaya mutu diidentifikasi. Terdapat 55 indikator atau item pengukuran dari 5 variabel tersebut yang telah dikembangkan menjadi kuesioner yang lengkap. Kuesioner dibagikan kepada seluruh karyawan di PT X, dengan total 25 tanggapan. Selanjutnya dilakukan pengolahan persentase maturity level pada PT X (dalam penelitian ini digunakan 5 level untuk mengukur kematangan budaya mutu yaitu: Ad hoc, Repeatable, Defined, Managed, dan Continuous) dan gap analysis pada setiap item pertanyaan yang kemudian akan dibandingkan dengan kondisi optimal sesuai validasi yang telah diperoleh dari pakar/ ahli dan hasil penelitian sebelumnya yang telah mengukur maturity level budaya mutu perusahaan konstruksi swasta nasional secara umum. Hasil pengolahan persentase maturity level budaya mutu pada PT X menunjukkan 59% matang dan berada pada level 4 (Terkelola) yang merupakan selisih 6% jika dibandingkan dengan hasil maturity level budaya mutu pada perusahaan konstruksi swasta nasional secara umum, yang menunjukkan 53% matang dan berada di level 3 (Terdefinisi). Berdasarkan analisis gap pada setiap item pertanyaan, ditemukan 21 indikator yang tidak memenuhi kriteria/ kondisi optimal yang diharapkan. Selanjutnya, direkomendasikan 15 strategi perbaikan untuk indikator yang tidak memenuhi kondisi optimal untuk meningkatkan maturity level yang mempengaruhi budaya mutu di PT X. Validasi pakar/ ahli dilakukan terhadap 15 rekomendasi strategi yang menyatakan bahwa semua pakar/ ahli setuju bahwa rekomendasi strategi dapat meningkatkan maturity level budaya mutu di PT X. Strategi peningkatan ini dikelola lebih lanjut dengan merekomendasikan prosedur pelaksanaan strategi yang kemudian dapat dikembangkan menjadi Standard Operational Procedures (SOP). Telah dibuat 15 rekomendasi prosedur/ aktifitas-aktifitas dalam menjalankan strategi dari hasil validasi sebelumnya dan dikembangkan 15 SOP berdasarkan prosedur/ aktifitas-aktifitas tersebut. Validasi pakar/ ahli dilakukan terhadap 15 rekomendasi prosedur dan SOP yang telah dikembangkan, yang menyatakan bahwa semua pakar/ ahli setuju bahwa rekomendasi prosedur dan SOP dapat digunakan dalam melaksanakan strategi meningkatkan maturity level budaya mutu di PT X, namun dengan beberapa saran dan masukan. Setelah dilakukan perbaikan terhadap saran dan masukan dari pakar/ ahli terdapat hasil akhir yaitu 12 SOP dalam melaksanakan strategi yang diperlukan untuk meningkatkan maturity level budaya mutu di PT X. Studi ini memberikan alat yang berharga bagi para peneliti untuk mendapatkan pemahaman yang lebih dalam tentang maturity level budaya mutu dan strategi peningkatannya. Bagi praktisi, sangat bermanfaat untuk mengevaluasi maturity level budaya mutu di dalam perusahaannya secara berkala, menargetkan perbaikan dan mengambil tindakan yang

mungkin dilakukan dalam upaya meningkatkan maturity level budaya mutu melalui strategi perbaikan yang telah dilakukan. Penelitian ini merupakan upaya pertama untuk mengukur maturity level budaya mutu dan mengembangkan standard operational procedures (SOP) dalam melaksanakan strategi meningkatkan maturity level budaya mutu pada perusahaan jasa pelaksana konstruksi swasta nasional di PT X

.....Abstract: The purpose of this paper is to make SOP recommendations in implementing the strategies needed to increase the maturity level that affects the quality culture at PT X. Based on a literature review of the quality culture maturity level and the content and construct validity assessment from practitioners, 5 variables to measure the quality culture maturity level identified. There are 55 indicators or measurement items from these 5 variables which have been developed into a complete questionnaire. Questionnaires were distributed to all employees at PT X, with a total of 25 responses. Furthermore, processing the percentage maturity level at PT X (in this study used 5 levels to measure the maturity of quality culture, namely: Ad hoc, Repeatable, Defined, Managed, and Continuous) and gap analysis on each question item which will then be compared with the optimal conditions according to validation that has been obtained from practitioners and the results of previous studies that have measured the level of maturity of the quality culture of national private construction companies in general. The results of processing the percentage maturity level at PT X show 59% mature and are at level 4 (Managed) which is a difference of 6% when compared to the results of the quality culture maturity level at national private construction companies in general, which is 53% mature and is at level 3 (Determined). Based on the gap analysis on each question item, 21 indicators were found that did not meet the expected optimal criteria/conditions. Furthermore, 15 improvement strategies are recommended for indicators that do not meet optimal conditions to increase the level of maturity that affects the quality culture at PT X. Expert validation was carried out on 15 strategic recommendations which stated that all experts agreed that strategy recommendations could increase the level of quality culture maturity at PT X. This improvement strategy is managed further by formulating a strategy implementation procedure which can then be developed into a Standard Operating Procedure (SOP). 15 recommended procedures/activities have been made in carrying out the strategy from the previous validation results and 15 SOPs have been developed based on these procedures/activities. Expert validation was carried out on 15 recommended procedures and SOPs that had been developed, which stated that all experts agreed that recommended procedures and SOPs could be used in implementing strategies to increase the maturity level of quality culture at PT X, but with some suggestions and input. After making improvements to suggestions and input from experts, the final result is 12 SOPs in implementing the strategies needed to increase the maturity level that affects the quality culture at PT X. This study provides a valuable tool for researchers to gain a deeper understanding of the maturity level. quality culture and improvement strategies. For practitioners, it is very useful to evaluate the maturity level of the quality culture within their company on a regular basis, target improvements and take possible actions in an effort to increase the maturity level that affects the quality culture through the improvement strategies that have been carried out. recommended. This research is the first attempt to measure the maturity level of quality culture and develop standard operational procedures (SOP) in implementing a strategy to increase the maturity level of quality culture in a national private construction service company at PT X.