

## Perilaku dan keamanan bendungan Notopuro akibat pengaruh longsor dan deformasi

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=121041&lokasi=lokal>

---

### Abstrak

A safety evaluation of the Notopuro dam in East java was carried out based on a combination of field inspection, instrument evaluation and slope stability analysis....