

Penelitian drainase jalan raya (Studi kasus ruas jalan Paliman - Jatibarang KM 33 + 100)

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=129296&lokasi=lokal>

Abstrak

Highways are often damaged by excessive water content below road surface. The road section between Palimanan - Jatibarang, West Java is an area often flooded particularly at left and right sides of road. To prevent floods, a study on these ditches had been implemented to determine the dimension of a ditch proportional with hydrological conditions in its vicinity....