

## Relationship between geomorphology and contamination with weathered hydrocarbons in an old river levee/marsh association

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=132198&lokasi=lokal>

---

### Abstrak

A site evaluation was made for a low-lying property in an old river levee/marsh association, used marginally for cattle raising, which was contaminated due to historical practices. Contamination was related to geomorphology: the lowest areas ...