

Kerusakan pada Relief Lalitavistara Candi Borobudur = The Damages of Lalitavistara's Relief at Borobudur Temple

Belinda Natasya, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20347626&lokasi=lokal>

Abstrak

Skripsi ini membahas mengenai bentuk kerusakan yang terdapat pada relief Lalitavistara Candi Borobudur. Tahapan penelitian dimulai dari pengidentifikasi jenis kerusakan seluruh panel relief Lalitavistara menggunakan satuan blok batu kemudian jumlah kerusakan diintegrasikan dengan adegan dan dinding candi agar diketahui dinding mana yang mengalami kerusakan terbanyak. Hasil Penelitian menunjukkan bahwa rata-rata jumlah kerusakan di setiap dinding hampir sama dan tidak ada satupun blok batu yang tidak mengalami kerusakan.

.....The focus consists of the forms of damage found on the Lalitavistara's relief of Borobudur. The first step of research is identifying the type of damage throughout Lalitavistara relief panels using the unit block of stone then it will be integrated with the amount of damage in scenes and the wall of the temple in order to know where the wall is damaged most. Research results showed average of damages on every wall in the same amount approximately and the damages occur in every block of stone.