

## Review of geological and mining condition at Ombilin, Indonesia, in comparison with those at other collieries, in Australia and the United Kingdom

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20407138&lokasi=lokal>

---

### Abstrak

This paper attempts to clarify the position of geological and mining conditions at Ombilin in comparison with those in Australia and the UK by examining both the technical strategy and its efficiency. A summary of this review is made to facilitate judgments on long wall layouts and strata control matters chosen during the stage of mine planning and design for purpose of the underground coal mine development in Indonesia.