

Penilaian risiko pada keselamatan penyeberang jalan di sekitar Jalan Kober dan Margonda Residence Depok tahun 2015 = Risk assessment on the safety of Pedestrians around Kober and Margonda Residence 2015

Marbun, Lidyarti, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20412200&lokasi=lokal>

Abstrak

Depok merupakan salah satu kota yang mempunyai kegiatan ekonomi yang semakin pesat dengan kawasan Margonda sebagai pusat kota utamanya seperti dengan adanya seperti terminal, pusat pertokoan, pusat pendidikan, serta tempat-tempat fasilitas umum lainnya. Keberadaan penyeberang jalan biasanya terdapat di tempat-tempat umum tersebut. Berdasarkan informasi dari Satlantas Kota Depok, tiap harinya terdapat 1-2 kecelakaan yang melibatkan penyeberang jalan di jalan Margonda padahal program dan pengendalian keselamatan penyeberang jalansudah dilakukan. Selain itu, Satlantas kota Depok belum melakukan pengendalian risiko yang berdasarkan pada kaidah manajemen risiko. Oleh karena itu dilakukan penelitian untuk menganalisis risiko keselamatan penyeberang di sekitar jalan Kober dan Margonda Residence.

Metode yang digunakan yaitu kualitatif bersifat deskriptif melalui wawancara mendalam dan observasi. Hasil penelitian menunjukkan tingkat risiko keselamatan penyeberang jalan di sekitar jalan Kober dan Margonda Residence yaitu 15 risiko sangat tinggi, 2 risiko tinggi, dan 3 risiko sedang.

.....

Depok is one of the cities that have economic activity is increasingly rapidly with Margonda region as its main city center such as the presence of such terminals, shopping centers, educational centers, and places of other public facilities. The existence of the pedestrian is usually found in public places such. Based on information from the Traffic Unit of Depok, every day there are 1-2 accidents involving safety pedestrians in Margonda although safety controls and programs have been implemented. Furthermore, Traffic Unit of Depok not perform risk control based on the principles of risk management. Therefore conducted a study to analyze the risk of pedestrian safety around the Kober and Margonda Residence. The method used is descriptive qualitative in-depth interviews and observation. The results showed the level of safety risk to pedestrians around the road Kober and Margonda Residence is 15 extreme risk, 2 high risk, and 3 moderate risk.