

ISTFA 2000: proceedings of the 26th International Symposium for Testing and Failure Analysis, 12-16 November 2000, Meydenbauer Convention Center, Bellevue, Washington

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20442548&lokasi=lokal>

Abstrak

Contents :

- Laser Voltage Probe (LVP): A Novel Optical Probing Technology for Flip-Chip Packaged Microprocessors
- Scanning Electron Acoustic Microscopy: A Novel Tool for Failure Analysis & Microcharacterisation
- Application of Single Contact Optical Beam Induced Currents (SCOBIC) for Backside Failure Analysis
- Measurement of Interfacial Adhesion and Its Degradation in Multi-Layer Packages, Devices, And Blanket Films Using the Laser Spallation Technique
- New FIB-Supported Approach for Wirebond Characterization
- Failure Analysis of Flip Chip Bumps after Thermal Stressing
- X-Ray Tomography for Electronic Packages
- Data Analysis Tools and Methodologies for Quick Yield Learning in a High Volume Manufacturing Environment
- Failure Analysis of Killer Defects and Yield Enhancement of Flat ROM Devices in Wafer Fabrication
- Embedded Memory Analysis for Standard Cell ASIC Yield Enhancement
- Yield Enhancement Study: Process Variation and Design Margins Leading to Timing Issues in RAM
- In-line Defect to Bitmap Signature Correlation: A Shortcut to Physical FA Results
- Analysis of Leakage Failures in Flash Memory Devices and Root Cause Identification
- Passive Voltage Contrast Application on Analysis of Gate Oxide Failure in 0.25 μm Technology
- Forensic Microscopy in the Failure Analysis Laboratory
- Failure Analysis Process Flow and Common Failure Mechanisms in Flip-Chip Packaged Devices
- A Study on the Yield Loss Due to Al (Cu) Interconnections with Spacing Failure
- Near IR Absorption in Heavily Doped Silicon—An Empirical Approach
- Embedded SRAM Bitmapping and Failure Analysis for Manufacturing Yield Improvement
- LSI Process Diagnosis for Device Users
- Application of KOH Electrochemical Etch and Passive Voltage Contrast Techniques to Identify Leaky Gate in Deep Submicron CMOS

- UV Reflectance Spectroscopy of the Copper/Copper Oxide System for Assessment of Solderability
- Antireflection Coatings for Semiconductor Failure Analysis
- Comparative Study of Sample Preparation Techniques for Backside Analysis
- A Comparison of Backside Emission Microscopy Systems
- Failure Analysis from the Back Side of a Die
- ESD Effects on Electromigration Performance of Aluminum Metallization System
- Evaluation of On-Chip ESD Supply Clamp Robustness by In-situ Floating Power Bus Monitoring
- Transmission Line Pulse Testing of the ESD Protection Structures of ICs.-A Failure Analysts Perspective
- Failure Analysis of CDM ESD Damage in a GaAs RFIC
- A Focused Ion Beam Technique to Electrically Contact the Deep Trench Capacitor of a Single Active Memory Cell in the Sub 0.25 μm Technology Regime
- The Use of TMAH to Etch Silicon and Expose Metal Bridging Failures
- Selective Au Etching in Au/Al Bonds in Current IC Technology
- A Novel Method to Analyze the Deep Trench Capacitors in DRAM
- Identification and Analysis of Parasitic Depletion Mode Leakage in a Memory Select Transistor
- Thermal Fatigue Induced Voiding in LDMOS Transistors Submitted to Multiple Energy Discharges
- Humidity-Bias Driven Shorts in Multilayer Circuits: A Case Study in Failure Analysis
- Passivation Cracks in a Four-Level Metal Low-k Dielectric Backend Process
- Electronic Package Failure Analysis Using TDR
- Time Domain Reflectometry as a Device Packaging Level Failure Analysis and Failure Localization Tool
- Contrast Inversions in Scanning Acoustic Microscopy (C-SAM) of Glue Die Attach
- Application of Scanning Acoustic Microscopy to Electric and Electronic Parts
- Combining FIB Sequential Cross-Sectioning With TEM for Small Defect Analysis in SRAM Array
- Failure Analysis of Tungsten Stud Defects from the CMP Process
- Integrated Circuit SNR Improvement using Dielectric Altering Compound, Laser Trim, and FIB system
- Characterization and Isolation Techniques in Silicon on Insulator Technology Microprocessor Designs
- Failure Analysis of Stacked-Chip Scale Package
- Reducing Top-of-Die Plastic Delamination by Assuring Pre-Mold Cleanliness of Die Surfaces
- SMT Ceramic Capacitor Failure Mechanisms, Isolation Tools, Techniques and Analysis Methods
- Case Studies of Brittle Interfacial Failures in Area Array Solder Interconnects

- Failure Analysis and Elimination of Galvanic Corrosion on Bondpads During Wafer Sawing
- High Temperature Solder (Au/Sn) Failures from Nickel Plating Impurities
- Semiconductor Wear Out at Nuclear Power Plants
- UTC Clinic Hospital Network: Description of International Network of Failure Analysis Labs and Case Studies
- Wafer Conserving Full Range Construction Analysis for IC Fabrication and Process Development Based on
- Index