

Analisis Aksesibilitas Pejalan Kaki pada Jalur Pedestrian yang Menghubungkan Station MRT Blok M dengan Terminal Bus Blok M = Analysis of Pedestrian Accessibility to The Pedestrian Path that Connected The MRT Block M Station With The Block M Bus Terminal

Khresna Putera Tama, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20445482&lokasi=lokal>

Abstrak

**ABSTRAK
**

Pembangunan Stasiun MRT Mass Rapid Transport di kawasan blok M akan lebih memudahkan masyarakat Jakarta dan luar kota Jakarta untuk mengunjungi tempat pemberlanjatan Blok M. Selain stasiun MRT yang akan dibangun, di kawasan Blok M juga telah tersedia terminal bus, baik itu bus biasa dan terminal bus way BRT koridor 1 yang berada pada lokasi yang sama. Dengan jumlah penumpang yang keluar di Stasiun MRT blok M sebanyak 26,612 orang per hari, jika tidak didukung dengan jalur pedestrian yang memadai tentunya mereka akan kesulitan untuk menuju terminal bus yang berada 300 meter dari stasiun MRT Blok M. Dengan keadaan situasi pedestrian yang ada di blok M sekarang, khususnya di jalan Melawai X yang menghubungkan stasiun MRT dan terminal bus. Maka tidak memungkinkan bagi penumpang yang berjalan kaki untuk menuju arah terminal bus dengan nyaman karena disepanjang jalan tersebut jalur pedestrian belum ada atau telah di alih fungsikan sebagai tempat berdagang atau parkir kendaraan. Maka dibutuhkan jalur pedestrian yang layak untuk para penumpang tersebut agar lebih mudah mengakses moda transportasi yang lain.

<hr>

**ABSTRACT
**

Construction of MRT Station Mass Rapid Transport on the Block M region will be facilitated public of Jakarta and outside Jakarta to visit central trade on Block M. In addition to the bus terminal on the Block M region has available, whether it is regular bus and bus way BRT first corridor in the same location. With the number of passengers that came out at the Block M MRT station as much as 26.612 people 's per day, if it is not supported by an adequate pedestrian path they would have difficulty to get to the bus terminal which is located 300 meters from the MRT station Blok M. With pedestrian situations in block M today, particularly at Melawai X street that connects the MRT station and bus terminal. Then it is not possible for passengers to walk towards the bus terminal comfortably, because along the street the pedestrian path does not exist or has been replaced it 's function as a trade or parking areas of vehicles. Then it takes a decent pedestrian path for the passengers to make them easier access to other transportation modes.