

## Gambaran hazard dan analisis risiko pada aktivitas maintenance wahana X di PT. Y tahun 2018 = Description of hazard and risk analysis of maintenance activity of ride X at company Y 2018

Pius Daviv Sugiarto, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20475237&lokasi=lokal>

---

### Abstrak

Penelitian ini bertujuan untuk mengetahui gambaran hazard dan analisis risiko pada aktivitas maintenance wahana X. Penelitian ini bersifat deskriptif dengan desain semi-kuantitatif dan menggunakan tahapan manajemen risiko AS/NZS: 4360. Tahapan kerja aktivitas maintenance didapatkan dari SOP dan wawancara mendalam. Analisis tingkat risiko menggunakan kriteria exposure, likelihood, consequence, dan risk level W.T. Fine. Aktivitas maintenance yang di analisis adalah harian dan mingguan greasing.

Hasil penelitian menunjukkan bahwa hazard terbanyak yang dihadapi oleh pekerja pada maintenance harian adalah hazard fisik ketinggian dan listrik dengan tingkat risiko tertinggi pada tahapan memeriksa neple dan oli hidraulik tentakel. Sementara untuk aktivitas greasing, hazard yang paling banyak adalah fisik ketinggian dengan tingkat risiko tertinggi pada tahapan kerja menuju lokasi penggantian grease. Adapun pengendalian yang telah dilakukan oleh perusahaan antara lain dengan pembagian shift kerja dan menyediakan kendaraan berupa golf car serta APD berupa; gloves, safety shoes, body harness, helm, dan googles.

*This study aims to determine the hazards and risks analysis that exist in the maintenance activities of the ride X. This research was conducted with semi quantitative design and using AS NZS 4360. Work process obtained from SOPs and in depth interviews. The criteria of level analysis exposure, possibilities, consequences, and risk level by W.T. Fine. The maintenance activities analyzed are daily and weekly greasing.*

*The results elucidate that most hazards incurred by workers for daily maintenance were physical hazards altitude and electrical at work process of inspection of the neple and tentacle hydraulic oil. Meanwhile, as for greasing activity, physical altitude is the most dangerous hazard at the work process to the location of grease replacement. In addition, controls that have been done by the company, among others, by dividing the work shift and providing the vehicle such as golf car and PPE in the form of gloves, safety shoes, body harness, helmets, and googles.*